

VOLTAGE BATTERY MAY MELT OR BURN

CAUSE:

RECALL GENERAL MOTORS HAS DECIDED THAT A DEFECT WHICH RELATES TO MOTOR VEHICLE SAFETY EXISTS IN SELECT 2017 - 2019 MODEL YEAR CHEVROLET BOLT EV VEHICLES. A SELECT NUMBER OF THESE VEHICLES WERE BUILT WITH HIGH VOLTAGE BATTERIES PRODUCED AT LG CHEM S OCHANG, KOREA FACILITY THAT MAY POSE A RISK OF FIRE WHEN CHARGED TO FULL, OR VERY CLOSE TO FULL, CAPACITY.

5171 WGM

(N/C)

17812 1.30

perform data inspection,, (volts ok) then perform hpcm2 reprogram
wcc=CBYN69988606...then reprogram BCM,,
wcc=OSYN69991245..perform set up,, then run dtcs,, and verify
operation as per recall.
labor op 9105420 1.1 + .2 =1.3 hr

B CUSTOMER STATES CS CLICKING NOISE BY THE BRAKES

30 TELL US MORE

5171 WGM

(N/C)

17812 0.30

verify concern,, clicking noise at brake pedalref pi 20-NA-170
perform brake booster module reprogram to fix concern
wcc=2BYN69865320
LABOR OP= 2811015 .3hr

C MULTI-POINT VEHICLE INSPECTION

DLR DLR

5171 WGM

(N/C)

WARRANTY DISCLAIMER: ALL PARTS AND ACCESSORIES ARE SOLD AND ALL REPAIRS ARE PROVIDED BY THE DEALERSHIP AS-IS. THE DEALERSHIP HEREBY EXPRESSLY DISCLAIMS ALL WARRANTIES, EXPRESS AND IMPLIED, INCLUDING ANY IMPLIED WARRANTIES OF MERCHANTABILITY AND FITNESS FOR A PARTICULAR PURPOSE, AND NEITHER ASSUMES NOR AUTHORIZES ANY OTHER PERSON TO ASSUME FOR IT ANY LIABILITY IN CONNECTION WITH THE SALE OF PARTS OR PRODUCTS OR THE REPAIR. THE ONLY WARRANTIES ON PARTS AND ACCESSORIES OR REPAIRS ARE THOSE WHICH MAY BE OFFERED BY THE MANUFACTURER OR THE ORIGINAL PARTS DISTRIBUTOR AND ONLY SUCH MANUFACTURER OR DISTRIBUTOR SHALL BE LIABLE FOR PERFORMANCE UNDER SUCH WARRANTIES. CUSTOMER SHALL NOT BE ENTITLED TO RECOVER FROM THE DEALERSHIP ANY CONSEQUENTIAL DAMAGES, DAMAGES TO PROPERTY, DAMAGES FOR LOSS OF USE, LOSS OF TIME, LOSS OF PROFIT OR INCOME, OR ANY OTHER INCIDENTAL DAMAGES.

By signing below, you acknowledge that you were notified of and authorized the Dealership to perform the services/repairs itemized in this invoice and that you received (or had the opportunity to inspect) any replaced parts as requested by you. The vehicle is being returned to you in exchange for your payment of the Amount Due.

***SHOP SUPPLY COSTS:**

We have added a charge equal to 3% of the total cost of labor and parts, not to exceed \$20.00, to the Repair Order for shop supplies used in connection with this repair.

**ALL PARTS ARE NEW
UNLESS OTHERWISE
INDICATED.**

DESCRIPTION

TOTALS

LABOR AMOUNT

PARTS AMOUNT

GAS, OIL, LUBE

SUBLET AMOUNT

MISC. CHARGES *

TOTAL CHARGES

LESS INSURANCE

SALES TAX

**PLEASE PAY
THIS AMOUNT**

DATE

CUSTOMER SIGNATURE

AUTHORIZED DEALERSHIP REPRESENTATIVE SIGNATURE